

	Type	Hits	Search Text	DBs
1	BRS	13950	Wheel same support same bearing	USPAT; EPO; JPO; DERWENT
2	BRS	3	Wheel same support same bearing same aluminum same (insulation or insulating)	USPAT; EPO; JPO; DERWENT
3	BRS	109	Wheel same support same bearing same aluminum	USPAT; EPO; JPO; DERWENT
4	BRS	1032	metal same corrosion same (prevention or preventing) same method	USPAT; EPO; JPO; DERWENT
5	BRS	0	metal same corrosion same (prevention or preventing) same method same (gasket or insulation) same wheel	USPAT; EPO; JPO; DERWENT
6	BRS	56	metal same corrosion same (prevention or preventing) same method same (gasket or insulation)	USPAT; EPO; JPO; DERWENT
7	BRS	0	301/11.01	USPAT; EPO; JPO; DERWENT
8	BRS	578	301/124.1	USPAT; EPO; JPO; DERWENT
9	BRS	383	384/589	USPAT; EPO; JPO; DERWENT
10	BRS	469	301/111	USPAT; EPO; JPO; DERWENT
11	BRS	144	301/137	USPAT; EPO; JPO; DERWENT

	Time Stamp	Co m m e n t s	Err or De fin iti on	Err or s
1	2004/03/17 11:19			0
2	2004/03/17 11:20			0
3	2004/03/17 11:51			0
4	2004/03/17 11:52			0
5	2004/03/17 11:52			0
6	2004/03/17 12:55			0
7	2004/03/17 12:03			0
8	2004/03/17 12:04			0
9	2004/03/17 12:04			0
10	2004/03/17 12:04			0
11	2004/03/17 12:05			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	0	seal same knuckle same electroconductive	USPAT; EPO; JPO; DERWENT	2004/03/17 14:19			0
2	BRS	L3	0	"electroconductive seal" same (wheel or axle)	USPAT; EPO; JPO; DERWENT	2004/03/17 14:20			0
3	BRS	L2	11	"electroconductive seal"	USPAT; EPO; JPO; DERWENT	2004/03/17 14:23			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L199	55	"71065"	USPAT; EPO; JPO; DERWENT	2004/03/17 12:56			0
2	BRS	L200	2	"71065" and corrosion	USPAT; EPO; JPO; DERWENT	2004/03/17 12:56			0
3	BRS	L201	0	2002-71065	USPAT; EPO; JPO; DERWENT	2004/03/17 12:56			0
4	BRS	L202	775	301/105.1	USPAT; EPO; JPO; DERWENT	2004/03/17 13:04			0
5	BRS	L203	14	knuckle same aluminum same bearing	USPAT; EPO; JPO; DERWENT	2004/03/17 13:04			0